

S E C R E T

ROUTING	
1	DM 9
2	10
3	11
4	12
5	Intell 13
6	14
7	15
8	16

IN 92956

OSA 1-20 7)

TO

INFO

CITE

HQS

HQS

HQS

HQS

HQS

HQS

HQS

HQS

HQS

HQS

25X1

25X1A

25X1A
25X1A
25X1A
25X1A

S E C R E T 020432Z CITE

IDEALIST AVION

REF

1. RE PARA 3. TCG DEFINITELY ON TAPE AND INTERMITTENT AS PREVIOUSLY STATED. APPEARS PROBLEM WAS DUE BAD PLAYBACK AMPLIFIER AT [] STEPS WILL BE TAKEN ENSURE THIS DOES NOT OCCUR AGAIN.

2. RE PARA 5. HAVE NO DEFINITE SUGGESTIONS, AS STATED TCG WILL NORMALLY SUFFICE.

3. P-BAND ALSO LOCATED HOWEVER, RECORDED ON TRACK OTHER THAN TRACK INDICATED.

4. SIGNAL LEVELS ALL APPEAR VERY GOOD WITH LITTLE SATURATION ENCOUNTERED. AS PREVIOUSLY STATED RECORDED SIGNALS MUCH BETTER THAN WHEN B UNIT USED.

S E C R E T TOR: 02/0502Z DEC 66